



Step One: Align Desks at a 90 degree angle

Step Two: Remove Glass Desk Tops


Step Three:(1) Remove Original Side Desk Bolts, (2) Position Metal Desk Connector
(3) Replace with Longer Bolts (4 Bolts- Supplied)



Four (4)
Replacement Bolts
(glass safety latch)



90° Angle
Metal Frame



90° Angle
Glass Top

**Step Four: Re-Position Glass Table Tops,
Position 90° Angle Glass Top**

